

Inspection Photos

API: 071-08417

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the location.



Inspection Photos



Photo 2. Facing toward the wellhead. There is a dripping leak at the well and standing water appears to have oily fluids comingled.



Inspection Photos



Photo 3. There are stained soils at the exhaust pipe and oily fluids inside the engine skid that need to be cleaned up.



Inspection Photos



Photo 4. Facing south along the fill slope.

