



00247806

WELL SITE INSPECTION FORM



WELL NAME Budin #1  
OPERATOR Kimbank  
LOCATION SE NW-3-8N-55W  
FIELD Coballo

API NUMBER 05 - 075 - 8705  
PERMIT NUMBER 78-0634  
COUNTY Logan  
INSPECTOR JP

AL/PA/DA INSPECTION RESULTS:

PASS(Y)  FAIL(N) \_\_\_\_\_ DATE 4/14/88

WELL STATUS:

FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_

CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_

RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

AL/PA/DA INSPECTION

DATE PLUGGED: 5/87 DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES  NO \_\_\_\_\_ PITS BACKFILLED: YES  NO \_\_\_\_\_

MATERIAL BURIED: YES  NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES  NO \_\_\_\_\_

BOND RELEASE OK: YES  NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO

DATE OF SAFETY/STATUS INSPECTION 5/19/87

COMMENTS Hole plugged, final cleanup leveling req'd.

10/9/87 No change - Spoke to Mr. Foster 10/13/87, will complete work

4/14/88 OK P&A check