

# Inspection Photos

December 16th, 2025

Operator: Hilcorp Energy

Location ID: 385910

Inspection Document #: 714003038

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Kaime 2-12 U-R  
Location ID: 385910



**Photo 1.** Aerial photo of the location taken with a drone during the time of the inspection from directly above the project area. Note: Entire project area has been outlined in blue. western portion which has not been reclaimed (indicated by red arrow) and Eastern portion of project area which appears to have been reclaimed per 1004 rules and standards (indicated by green arrow).

Inspection Photos  
Location Name: Kaime 2-12 U-R  
Location ID: 385910

December 16, 2025  
254° W



**Photo 2.** View of the western portion of the project area taken at ground level from the southern edge facing west.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

December 16, 2025  
145° SE



**Photo 3.** View of the the western portion of the project area taken from the northern edge facing south east. Note: Additional berm has been constructed on the southern edge of the western project area (indicated by red arrow). It was noted that surface owner equipment has been removed but western portion of the project area still remains unreclaimed per 1004 rules.

December 16, 2025  
359° N



**Photo 4.** View of well marker on the eastern side of the project area. This portion of the project area has been reclaimed and appears consistent with adjacent reference areas.

Inspection Photos  
Location Name: Kaime 2-12 U-R  
Location ID: 385910

December 16, 2025  
356° N



**Photo 5.** View of adjacent reference area.