

INSPECTION PHOTOS

Well: G.K.S 33-29

API #: 05-071-06303

INSPECTION DOC #: 716301910

Operator: Pioneer Natural Resources LLC. 10705

Inspection date: 1/5/2026

County: Las Animas

EVERGREEN
NATURAL RESOURCES LLC

G.K.S 33-29

API 05-071-06303

NW/SE 29 32S66W 6

LAT. 37.22718/LONG -104.79912

Emergency Number: 911 or (719) 846-7898

LAT. 37.22718 / LONG. -104.79912

COC59968A

Network: Jan 5, 2026 at 12:58:56 PM MST

Local: Jan 5, 2026 at 12:58:56 PM MST

+37.227405,-104.799258

Las Animas County

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO DRAIN OILY WASTE 1/6/2026, 10 DAYS TO REMOVE IMPACTED SOILS. 1/16/2026.