

# INSPECTION PHOTOS

Well: ANTONIO 23-29

API #: 05-071-06802

INSPECTION DOC #: 716301912

Operator: Pioneer Natural Resources LLC. 10705

Inspection date: 1/5/2026

County: Las Animas




PHOTO 2: WELL SIGN



Network: Jan 5, 2026 at 1:27:15 PM MST  
Local: Jan 5, 2026 at 1:27:15 PM MST  
+37.226765, -104.806329  
Las Animas County

PHOTO 3: LOCATION.



PHOTO 4: KVWELLHEAD AND EQUIPMENT.



PHOTO 5: TR WELLHEAD AND EQUIPMENT.



**PHOTO 6: LESS THAN 2" OF FREEBOARD IN TR WELLS PIT. Lower fluid level so at least two feet of freeboard exists per Rule 909.c. CA DATE 1/6/2025.**