

# Inspection Photos

API: 071-06404

Operator: OGRIS OPERATING LLC

Inspection Date: 12/30/2025

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing southwest along the reclaimed access road.



## Inspection Photos



**Photo 2.** Facing northwest along the reclaimed access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06404 | Date: 12/30/2025

## Inspection Photos



**Photo 3.** Facing north toward the reclaimed location. Perennial vegetation has re-established to reference area levels.



## Inspection Photos



**Photo 4.** Center of the location facing south.



## Inspection Photos



**Photo 5.** Facing south toward the reclaimed location. Perennial vegetation has re-established to reference area levels.

