

Final Reclamation Inspection

September 4th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 329953

Inspection Document #: 714003131

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-Sandlin 3-36

Location ID: 329953



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle), associated tank battery location (blue polygon), and access road (black line). The tank battery is associated with its own location ID #445906.



Inspection Photos

Location Name: HSR-Sandlin 3-36

Location ID: 329953



Photo 2. Orthomosaic (drone) imagery taken 9/4/2025 and NAIP aerial imagery (2023) illustrating the well locations (red circles) and associated tank battery location (blue polygon).



Inspection Photos

Location Name: HSR-Sandlin 3-36

Location ID: 329953



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well and access road. Note stunting all over field).



Inspection Photos

Location Name: HSR-Sandlin 3-36

Location ID: 329953



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well. Note stunting all over field).





Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well and access road).

Inspection Photos

Location Name: HSR-Sandlin 3-36

Location ID: 329953



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well, estimated flowline).

