

Final Reclamation and Stormwater Inspection

December 29, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320228

Well Name: DEGENHART #3

Inspection Document #: 718601278

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DEGENHART #3
Location ID: 320228



Photo 1. Looking west west across the location. The culvert and gravel has been removed from the location. All oil and gas equipment has been removed from the location. It appears that reclamation has been conducted on the location.



Photo 2. A well marker is present on location.



Inspection Photos
Location Name: DEGENHART #3
Location ID: 320228



Photo 3. Looking north from the wellbore. Some desirable perennial vegetation is present but sparse on location. Bare soil is visible on location along with undesirable weeds such as blue mustard (*Chorispora tenella*).



Photo 4. Looking west from the wellbore. See photo 3 comments.



Inspection Photos
Location Name: DEGENHART #3
Location ID: 320228



Photo 5. Looking south from the wellbore. See photo 3 comments.



Photo 6. Looking east from the wellbore across the storage tank area. See photo 3 comments.



Inspection Photos
Location Name: DEGENHART #3
Location ID: 320228



Photo 7. Looking east across the location from the west side. Two monitoring wells are present on the location.



Photo 8. Reference vegetation to the south of the location.



Inspection Photos
Location Name: DEGENHART #3
Location ID: 320228




Photo 9. Google earth aerial imagery taken 03/2025. A portion of the former disturbance area (Green circle) appears to have been disturbed by housing development.

