

Inspection Photos

API:061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/5/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo east along the former access road that has not been reclaimed.



Inspection Photos



Photo 2. Drone aerial photo facing along the access road that was not reclaimed.



Inspection Photos



Photo 3. Drone aerial photo facing north overlooking the reclaimed portion of the road and location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/5/2026

Inspection Photos



Photo 4. Drone aerial photo facing northwest toward the former tank battery location.



Inspection Photos



Photo 5. Drone aerial photo facing northeast toward the former wellsite location.



Inspection Photos



Photo 6. Drone aerial photo facing northeast at the location. There is mostly undesirable weed at the location. Reseeding will need to be performed.



Inspection Photos



Photo 7. Drone aerial photo facing south toward the location and access road.

