

Inspection Photos
Location Name: Quinby 61S69W 12SWNE
Location ID: 321356



Photo 1 Location entrance.

Photo 2 Tank battery location.

Inspection Photos
Location Name: Quinby 61S69W 12SWNE
Location ID: 321356




Photo 3 Gas Meter run, card indicates current calibration.

Photo 4 Horizontal Heated Separator.

Inspection Photos
Location Name: Quinby 61S69W 12SWNE
Location ID: 321356




Photo 5 Flow lines, valves are shut.

Photo 6 ECD.

Inspection Photos
Location Name: Quinby 61S69W 12SWNE
Location ID: 321356



Photo 7 Tank battery/signs.

Photo 8 Tank battery.