

Inspection Photos
Location Name: Ocoma 31-25
Location ID: 332875



Photo 1 well head and equipment




Photo 2 well head master valve leaking