


**Inspection Photos**  
**Location Name: Ocoma 31-26**  
**Location ID: 332668**



**Photo 1 well head and equipment**



**Photo 2 well head master valve leaking**