

# Inspection Photos

12/31/2025

**Operator:** QB Energy Operating LLC #10844

**Location ID:** 334630

**Inspection Doc:** 719200624

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334630



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334630



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334630



**Photo 3:** Photos showing an overview of the western interim area. Interim areas are heavily used by livestock and grazing pressure is evident. A follow-up inspection will be conducted during future growing seasons to assess vegetation.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334630



**Photo 4:** Photos showing an overview of the western interim area. Interim areas are heavily used by livestock and grazing pressure is evident. A follow-up inspection will be conducted during future growing seasons to assess vegetation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources