ORIGINS LABORATORY

ORIGINS WORK ORDER #

Page 1 of 1

Client: Chevron - CO

Address: 2115 117th Avenue; Greeley, CO 80634

Telephone Number: Dan Peterson (970) 730-7281

Email Address: NorthernColoradoPM@montrose-env.com
RBUEF27@Chevron.com

Project Manager: Christa Welch (405) 317-1628

Project Name: Wolfe USX CC07-16

Project Number: 33389

Collected By: KW, ST, DL

Invoice/Billing Info: Bill to Chevron; Dan Peterson; (970) 730-7281
2115 117th Avenue, Greeley, CO 80634

Key:
W= Water
GW=Groundwater
SW=Surface Water
WW=Waste Water
L=Liquid

S=Soil | SO=Solid | O=Oil | A=Air | G=Gas || UNP=Unpres | HCL= Hydrochloric | HNO3=Nitric | H2SO4=Sulfuric | NAOH=Sodium Hydroxide

#	Sample ID	Date Sampled	Time Sampled	# of Containers	Matrix	Preservative	Analysis: 8015-ext	Analysis	Analysis	Analysis	Analysis	Analysis	Analysis	Analysis	Analysis	Analysis	Analysis	Comments
1	SEP01-DL-SB@2'	12/31/25	1051	3	S	UNP	X											
2	SEP01-DL-SB@4'	12/31/25	1101	3	S	UNP												
3	SEP01-DL-SB01@3'	12/31/25	0928	3	S	UNP												
4	SEP01-DL-SB02@3'	12/31/25	1040	3	S	UNP												
5	SEP01-DL-SB03@3'	12/31/25	0922	3	S	UNP												
6	SEP01-DL-SB04@3'	12/31/25	1012	3	S	UNP												
7																		
8																		
9																		
10																		

Relinquished By:	Date:	Time:	Received By:	Date:	Time:
[signature]	12/31/25	1240			
Relinquished By:	Date:	Time:	Received By:	Date:	Time:

Turnaround Time
- ☐ SAME DAY
- ☐ 24 Hr
- ☐ 48 Hr
- ☐ 72
- ☒ Standard

For Lab Sample Receving Only:

Temp Received-

Received On Ice? ☐ Yes ☐ No