

Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 332813

Inspection Document #: 718801172

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WOLF-64N66W/31SESE
Location ID: 332813



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: WOLF-64N66W/31SESE
Location ID: 332813



Photo 3. Photo taken of the multi-well location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west.
See comments under Photo 1.

Inspection Photos
Location Name: WOLF-64N66W/31SESE
Location ID: 332813



Photo 5. Photo taken of ground cover at the multi-well location. Photo illustrates bare ground and perennial grass with evidence of drill row seeding.



Photo 6. Photo taken of the tank battery location, facing southwest. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards.

Inspection Photos
Location Name: WOLF-64N66W/31SESE
Location ID: 332813



Photo 7. Photo taken of the tank battery location, facing southeast. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing north. See comments under Photo 6.

Inspection Photos
Location Name: WOLF-64N66W/31SESE
Location ID: 332813



Photo 9. Photo taken of ground cover at the location. Photo illustrates bare ground and perennial grass.



Photo 10. Photo taken of the reference area to the location, north of the multi-well location, facing north. Photo illustrates perennial grass and weedy annual vegetation.