

Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 470544

Inspection Document #: 718801166

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FARR FARMS #1
Location ID: 470544



Photo 1. Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and bare ground and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the tank battery location, facing north. See comments under Photo 1.

Inspection Photos
Location Name: FARR FARMS #1
Location ID: 470544



Photo 3. Photo taken of the tank battery location, facing northeast. Photo illustrates a water well remains on site.



Photo 4. Photo taken of the tank battery location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: FARR FARMS #1
Location ID: 470544



Photo 5. Photo taken of ground cover at the location. Photo illustrates bare ground and kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

