

# Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 309694

Inspection Document #: 718801184

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STROH #5  
Location ID: 309694



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: STROH #5  
Location ID: 309694



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: STROH #5  
Location ID: 309694



**Photo 5.** Photo taken of the access road to the location, facing south, towards the location. Photo illustrates that final reclamation activities have not taken place and gravel and bare ground remain across the road.



**Photo 6.** Photo taken of the access road to the location, facing west, towards the location. Stormwater erosion was observed along the edge of the road (highlighted in red).

Inspection Photos  
Location Name: STROH #5  
Location ID: 309694



**Photo 7.** Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation activities appear to have taken place, but the location does not meet Rule 1004 standards as weedy annual vegetation was observed across the location.



**Photo 8.** Photo taken of the tank battery location, facing south. See comments under Photo 7.



Inspection Photos  
Location Name: STROH #5  
Location ID: 309694



**Photo 9.** Photo taken of the tank battery location, facing east. See comments under Photo 7.



**Photo 10.** Photo taken of the reference area to the location, west of the location, facing southwest. Photo illustrates perennial grass and shrub vegetation.

