

Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 322854

Inspection Document #: 718801170

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FARR FARMS #1
Location ID: 322854



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and bare ground and weedy annual vegetation including kochia (*Bassia scoparia*) were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: FARR FARMS #1
Location ID: 322854



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: FARR FARMS #1
Location ID: 322854



Photo 5. Photo taken of ground cover at the location. Photo illustrates bare ground and kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.