

Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 332487

Inspection Document #: 718801182

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STROH #24-12
Location ID: 332487



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: STROH #24-12
Location ID: 332487



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: STROH #24-12
Location ID: 332487



Photo 5. Photo taken of the access road to the location, facing northwest, towards the location. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. A concrete barrier has been implemented along the access road.



Photo 6. Photo taken of the access road to the location, facing northwest, towards the location. Stormwater erosion was observed along the southeastern portion of the road.



Inspection Photos
Location Name: STROH #24-12
Location ID: 332487



Photo 7. Photo taken of ground cover at the access road. Photo illustrates stormwater erosion.



Photo 8. Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass and weedy annual vegetation.