

# Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 327347

Inspection Document #: 718801196

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: ORR #24-1  
Location ID: 327347



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but the location has been recently mowed, so vegetation establishment will be determined in an inspection at a later date.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: ORR #24-1  
Location ID: 327347



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: ORR #24-1  
Location ID: 327347



**Photo 5.** Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation activities appear to have taken place. However, the location has been recently mowed, so vegetation establishment will be determined in a future inspection.



**Photo 6.** Photo taken of the tank battery location, facing south. See comments under Photo 5.

Inspection Photos  
Location Name: ORR #24-1  
Location ID: 327347



**Photo 7.** Photo taken of the tank battery location, facing north. See comments under Photo 5.



**Photo 8.** Photo taken of the ground cover at the tank battery location. Photo illustrates perennial grass and weedy annual vegetation including Kochia (*Bassia scoparia*).



Inspection Photos  
Location Name: ORR #24-1  
Location ID: 327347



**Photo 9.** Photo taken of the reference area to the location, south of the location, facing east. Photo illustrates perennial grass vegetation.

