

Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 472039

Inspection Document #: 718801180

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Stroh #24-12
Location ID: 472039



Photo 1. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*) were observed across the location.



Photo 2. Photo taken of the tank battery location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: Stroh #24-12
Location ID: 472039



Photo 3. Photo taken of the tank battery location, from the adjacent road, facing north. See comments under Photo 1.



Photo 4. Photo taken of the reference area to the location, northwest of the location, facing west. Photo illustrates perennial grass and weedy annual vegetation.

