

# Final Reclamation Inspection

December 16, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 447144

Inspection Document #: 718801194

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Orr #33-24  
Location ID: 447144



**Photo 1.** Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the tank battery location, facing northwest. See comments under Photo 1.

Inspection Photos  
Location Name: Orr #33-24  
Location ID: 447144



**Photo 3.** Photo taken of the tank battery location, facing southwest. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing southeast. See comments under Photo 1.

Inspection Photos  
Location Name: Orr #33-24  
Location ID: 447144



**Photo 5.** Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including puncture vine (*Tribulus terrestris*), a List C Noxious Weed species.



**Photo 6.** Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass that has been mowed.

Inspection Photos  
Location Name: Orr #33-24  
Location ID: 447144



**Photo 7.** Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass that has been mowed.

