

Inspection Photos

API:061-06792

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/5/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the former access road which is swalled and not recontoured.



Inspection Photos



Photo 2. Facing south toward the abandoned wellsite. An open excavation remains at the location.



Inspection Photos



Photo 3. Facing southwest. The location has not been reclaimed back to cropland.

