

# INSPECTION PHOTOS

Well: McDONALD 33-31 R

API #: 05-071-08533

INSPECTION DOC #: 716301928

Operator: Pioneer Natural Resources LLC. 10705

Inspection date: 1/7/2026

County: Las Animas





Network:Jan 7, 2026 at 11:14:17 AM MST  
Local:Jan 7, 2026 at 11:14:17 AM MST  
+37.211873,-104.818285  
Las Animas County

PHOTO 3: LOCATION.



Network: Jan 7, 2026 at 11:14:43 AM MST  
Local: Jan 7, 2026 at 11:14:43 AM MST  
+37.211496, -104.818328  
Las Animas County

PHOTO 4: WELLHEAD AND EQUIPMENT.