

# INSPECTION PHOTOS

**Well: GOLDEN EAGLE 21-10**

**API #: 05-071-08417**

**INSPECTION DOC #: 716301926**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 1/8/2026**

**County: Las Animas**



**OGRIS**  
OPERATING, LLC

PERMIT 71305

(719) 868-2703

or 911

GOLDEN EAGLE 21-10

NW/SE 21-33S-67W

NAD 83

Lat. 37.156674

Long. 104.888685

Network: Jan 8, 2026 at 12:07:35 PM MST  
Local: Jan 8, 2026 at 12:07:35 PM MST  
+37.156682, -104.888592  
Las Animas County

PHOTO 2: API # IS NOT POSTED ON WELL SIGN AND CONTACT PHONE NUMBER IS FADED AND NOT LEGIBLE. **POST SIGN PER RULE 605. CA DATE 2/8/2026.**



Network: Jan 8, 2026 at 12:06:19 PM MST  
Local: Jan 8, 2026 at 12:06:19 PM MST  
+37.156385,-104.888804  
Las Animas County

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: There is a dripping leak at the wellhead and a pool of water at wellhead with an oily sheen. **Control and contain spills/releases and clean up per Rule 912.a. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**



**PHOTO 6: There is oily fluids in the engine skid and stained material at the engine exhaust pipe. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**



Network: Jan 8, 2026 at 12:08:03 PM MST  
Local: Jan 8, 2026 at 12:08:03 PM MST  
+37.156690, -104.888627  
Las Animas County

**PHOTO 7: There is oily fluids in the engine skid and stained material at the engine exhaust pipe. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CA IMMEDIATE ACTION IS REQUIRED.**