

INSPECTION PHOTOS

Well: GOLDEN EAGLE 21-07

API #: 05-071-7680

INSPECTION DOC #: 716301930

Operator: OGRIS OPERATING LLC 10758

Inspection date: 1/8/2026

County: Las Animas



OGRIS
OPERATING, LLC

(719) 848-0272
or 911

INC.

GOLDEN EAGLE 21-07

SW NE SEC. 21-33S-67W

NAD 83

WDID 1912340
PERMIT 71271

LAT. 37.16014

LONG. 104.88948

Network: Jan 8, 2026 at 1:16:47 PM MST
Local: Jan 8, 2026 at 1:16:47 PM MST
+37.160039, -104.889446
Las Animas County

PHOTO 2: NO API # POSTED ON WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.




PHOTO 5: IMPACTED SOIL NEAR LEAKING DRIVEHEAD. REPAIR LEAKS & Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 1/20/2026.



PHOTO 6: OILY WASTE IN PRIME MOVER SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 24 HOURS TO DRAIN OILY WASTE 1/9/2026, 10 DAYS TO REMOVE IMPACTED SOIL 1/20/2026.