

INSPECTION PHOTOS

Well: GOLEN EAGLE 21-03 & CH

API #: 05-071-07994

INSPECTION DOC #: 716301934

Operator: OGRIS OPERATING LLC 10758

Inspection date: 1/8/2026

County: Las Animas



PHOTO 2: API # IS NOT POSTED ON EITHER WELL SIGNS.



Network: Jan 8, 2026 at 2:09:46 PM MST
Local: Jan 8, 2026 at 2:09:46 PM MST
+37.161559, -104.895581
Las Animas County

PHOTO 3: LOCATION.



PHOTO 4: ORIGINAL WELLHEAD AND EQUIPMENT.



PHOTO 5: CH WELLHEAD AND EQUIPMENT./ Vacuum pump observed on CH well without ECMC approval. Provide ECMC with documentation showing approval of use of vacuum pump. CA DATE 1/26/2026.



Network: Jan 8, 2026 at 2:10:13 PM MST
Local: Jan 8, 2026 at 2:10:13 PM MST
+37.161602, -104.895403
Las Animas County

PHOTO 6: DEBRIS AROUND PIT (OLD ROTTING LOG FENCE). REMOVE ALL DEBRIS PER RULE 606. CA DAT 1/20/2026.