


# Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-31-11 Pad

Location ID: 335090



Jan 8, 2026 at 2:41:37 PM  
+39.499328,-108.242169  
28° NE  
Garfield County



Jan 8, 2026 at 2:44:08 PM  
+39.499456,-108.242026  
79° E  
Garfield County

Permit No.: GP01  
RS ID: 045/0975/00

**LARAMIE ENERGY LLC**  
NWNE Sec 29 T6S R97W  
Accessed from Conn Creek Road,  
Garfield County, CO  
**Emergency Contact 1-800-891-6191 or 911**  
**WELLS SERVICED BY THIS TANK BATTERY**

CC 697-20-59D	05-045-11814	NWNE Sec 29 T6S R97W
CC 697-29-15DX	05-045-11816	NWNE Sec 29 T6S R97W
CC 697-29-20D	05-045-11815	NWNE Sec 29 T6S R97W
CC 697-29-22D	05-045-12181	NWNE Sec 29 T6S R97W
CC 629-31-11	05-045-07811	NWNE Sec 29 T6S R97W

Photo # 9653 From entrance to location

Photo # 9654 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-31-11 Pad

Location ID: 335090



Photo # 9655 Location



Photo # 9656 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-31-11 Pad

Location ID: 335090



Photo # 9657 Location



Photo # 9658 Location

# Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-31-11 Pad

Location ID: 335090



Photo # 9659 Mechanical Condition - Possible leak on tank valve



Photo # 9660 Mechanical Condition - Possible leak on tank valve

# Inspection Photos

Location Name: LARAMIE ENERGY LLC CC 0629-31-11 Pad

Location ID: 335090



Photo # 9661 Mechanical Condition - Possible leak on tank valve

Photo # 9662 Mechanical Condition - Possible leak on tank valve