

# Final Reclamation Inspection

September 8th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 310569

Inspection Document #: 714003146

Weld County, CO

Corey Mcdonough  
Reclamation Specialist, ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Frank 24-31

Location ID: 330256



**Photo 1.** NAIP aerial imagery (2011) illustrating the well location (red circle) and associated tank battery location (blue polygon). The tank battery is associated with location ID #330256.





**Photo 2.** NAIP aerial imagery (2023) illustrating the well location (red circle), and associated tank battery (blue polygon).

Inspection Photos

Location Name: Frank 24-31

Location ID: 330256



**Photo 3.** Drone aerial imagery taken south of well location, facing north (displaying the well).



Inspection Photos

Location Name: Frank 24-31

Location ID: 330256



**Photo 4.** Drone aerial imagery taken west of well location, facing east (displaying the well). Crop vegetation at the well pad appears consistent with adjacent reference areas.



Inspection Photos

Location Name: Frank 24-31

Location ID: 330256



**Photo 5.** Drone aerial imagery taken north of well location, facing south (displaying the well).





**Photo 6.** Drone aerial imagery taken east of well location, facing west (displaying the well and estimated flowline).