

Inspection Photos

01/07/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334344

Inspection Doc: 719200641

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334344



Photo 1: Photos showing an overview of the location looking northwest and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334344



Photo 2: Photos showing an overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334344



Photo 3: Photos showing trash and debris that is present in the southern interim area and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334344



Photo 4: Photos showing examples of the wellhead sign plate that has slipped and is no longer able to be read from outside of the fenced wellhead area. Maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334344



Photo 5: Photos showing an overview of the western and southern interim areas. Interim areas appear to be progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources