

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CASS-GARBER-68S96W/1NWNE

Location ID: 334129

Date: 1/7/2026



Location Overview – Photo #02233



Location – Photo #02237

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CASS-GARBER-68S96W/1NWNE

Location ID: 334129

Date: 1/7/2026



Location – Photo #02235



Location – Photo #02234

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CASS-GARBER-68S96W/1NWNE

Location ID: 334129

Date: 1/7/2026



Lack of Stabilization – Photo #02238



Lack of Stabilization/Insufficient Tracking BMPs – Photo #02239