

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9)

Location #: 334980



Photo # 7866 From entrance to location




Photo # 7867 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9)

Location #: 334980



Photo # 7868 Location



Photo # 7869 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9)

Location #: 334980




Photo # 7870 Location



Photo # 7871 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9)

Location #: 334980



Photo # 7872 Barbed wire fence needs maintenance/wildlife hazard



Photo # 7873 Barbed wire fence needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 11C-7 (Mesa 9)

Location #: 334980



Photo # 7874 Barbed wire fence needs maintenance/wildlife hazard