


Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



3. View looking inside of wellhead fencing.



4. View looking east towards wellhead location.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



5. View looking west towards wellhead location.



6. Steel separator/meter shed at production facility.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



7. 2-Phase separator.



8. Chart Recorder.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



9. View of produced water tank at remote production location.



10. Concrete vault containing water transfer pump.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



11. Production facility looking east.



12. Production facility looking south.

Inspection Photos
Location Name: Bledsoe 9-33-5-44 (OWP)
API Number: 125-09700



13. Production facility looking west.



14. Production facility looking north.