

# Inspection Photos

01/07/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334872

Inspection Doc: 719200655

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334872



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334872



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334872



**Photo 3:** Photos showing an overview of the eastern and northwestern interim areas, respectively. Interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334872



**Photo 4:** Photos showing example of trash and debris that is scattered throughout the eastern interim area. Removal is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334872



**Photo 5: Photo showing Remediation Project #17035.**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources