

Inspection Photos  
Location Name: Brophy M 5-25  
API Number: 125-08958



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos  
Location Name: Brophy M 5-25  
API Number: 125-08958



3. Well location overview.



4. Lease sign at gathering location.

**Inspection Photos**  
**Location Name: Brophy M 5-25**  
**API Number: 125-08958**



**5. Gas Meter inside Meter Shed.**



**6. Gathering location overview.**