


Inspection Photos  
Location Name: Yenter C 2-21  
API Number: 125-07157



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos  
Location Name: Yenter C 2-21  
API Number: 125-07157



3. Well location overview.



4. Lease sign at gathering location.

**Inspection Photos**  
**Location Name: Yenter C 2-21**  
**API Number: 125-07157**



**5. Gas Meter inside Meter Shed.**



**6. View of produced water tank at remote gathering location.**

**Inspection Photos**  
**Location Name: Yenter C 2-21**  
**API Number: 125-07157**



**7. View of broken ground strap on production tank.**



**8. Gathering location overview.**