

Inspection Photos
Location Name: Wise F Unit 1
Location ID: 321334



Photo 1 Location entrance.

Photo 2 Tank battery.

Inspection Photos
Location Name: Wise F Unit 1
Location ID: 321334



Photo 3 Tank battery.

Photo 4 Tank battery sign is fading and will need to be updated.

Inspection Photos
Location Name: Wise F Unit 1
Location ID: 321334



Photo 5 Wellsite.

Photo 6 Wellsite sign.

Inspection Photos
Location Name: Wise F Unit 1
Location ID: 321334



Photo 7 Wellsite.



Photo 8 Horizontal Heated Separator.