

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 297 From entrance to location

Photo # 298 From entrance to location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729




Photo # 299 Location



Photo # 300 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 301 Location



Photo # 302 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 303 Location



Photo # 304 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 305 Location



Photo # 306 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 307 Location



Photo # 308 Tank label damaged & illegible

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-12A Pad

Location #: 335729



Photo # 309 Debris