

# Inspection Photos

API: 071-08699

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/12/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the wellsite..



## Inspection Photos



**Photo 2.** well sign is posted at the meter shed.



## Inspection Photos



**Photo 3.** Facing southwest toward the wellsite.



## Inspection Photos



**Photo 4.** Facing north along the west fill slope which is stabilized with perennial vegetation.

