

Final Reclamation Inspection

September 10th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 336093

Inspection Document #: 714003189

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. NAIP aerial imagery (2013) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road (black line). The tank battery is associated with location ID #488944 and remains active.

Inspection Photos
Location Name: Jim 1
Location ID: 336093




Photo 2. NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).

Inspection Photos
Location Name: Jim 1
Location ID: 336093



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).



Inspection Photos
Location Name: Jim 1
Location ID: 336093



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well).





Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well and access road). Crop vegetation at the well pad and access road appears consistent with adjacent reference areas.





Photo 7. Drone aerial imagery directly above the well location, facing downward (displaying the well).

Inspection Photos
Location Name: Jim 1
Location ID: 336093



Photo 8. Drone aerial imagery taken southeast of the well location, facing northwest (displaying the well and presumed flowline).



Inspection Photos
Location Name: Jim 1
Location ID: 336093



Photo 9. Drone aerial imagery taken west of the well access road takeoff, facing east (displaying the well access road and well).





Photo 10. Drone imagery of active tank battery.