

Final Reclamation Inspection

September 18th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 326818

Inspection Document #: 714003247

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Daniel V-11-16

Location ID: 326818




Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle), associated tank battery location (blue polygon), and well access road (black line). The tank battery is associated with location ID #450468.



Inspection Photos

Location Name: Daniel V-11-16

Location ID: 326818



Photo 2. Orthomosaic (drone) imagery taken 9/18/2025 and NAIP aerial imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Inspection Photos

Location Name: Daniel V-11-16

Location ID: 326818



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well and part of the access road).



Inspection Photos

Location Name: Daniel V-11-16

Location ID: 326818



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).



Inspection Photos

Location Name: Daniel V-11-16

Location ID: 326818



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well and access road).





Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).



Photo 7. Drone aerial imagery taken northwest of well location, facing southeast (displaying the well and presumed flowline).