

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404510132

Date Received:  
01/16/2026

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Waggoner, Kyle</u>		<u>kyle.waggoner@state.co.us</u>
<u>Brown, Kari</u>		<u>kari.oakman@state.co.us</u>
<u>Collins, Kilian</u>		<u>kilian.collins@state.co.us</u>
<u>Graber, Nikki</u>		<u>nikki.graber@state.co.us</u>
<u>Kirschner, Steven</u>		<u>steven.kirschner@state.co.us</u>
<u>-</u>		<u>rbucogccinspectionreports@chevron.onmicrosoft.com</u>
<u>Peterson, Dan</u>		<u>danpeterson@chevron.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718300108

Inspection Date: 10/30/2025 FIR Submit Date: 11/12/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 13 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.311263 Longitude: -104.496676

FACILITY - API Number: 05-123-00 Facility ID: 491851

Facility Name: Sater 32-13 Number: \_\_\_\_\_

Qtrqtr: SWNE Sec: 13 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.311263 Longitude: -104.496676

CORRECTIVE ACTIONS:

**2** CA# 209356

Corrective Action:

Date: 11/19/2025

Per Rule 912.a.(2): Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered. Per Rule 913.d.(1): Operators will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Based on Operator documentation the suspected release was discovered during facility decommissioning on 9/11/2025. Per Rule 912.b.(1). The Initial Spill/Release Report must be submitted within 24 hours of discovery. The Initial Form 19 was received on 10/28/2025, 47 days late. Operator shall provide explanation for late report on the next Form 19 Supplemental including actions implemented to prevent late reporting in the future. The Operator is directed to submit a replacement Form 19 immediately and no later than 11/19/2025.

Response: CA COMPLETED

Date of Completion: 12/19/2025

Operator Comment: Form 19 submitted 12/19/2025 doc #404464723.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**4** CA# 209358

Corrective Action: Submit a Supplemental Form 27 to include an updated implementation schedule in addition to proposed specific actions to address the identified releases. Note: Form 27s Doc #404411658 was received on 11/11/2025 and has been returned to draft.

Date: 11/19/2025

Response: CA COMPLETED

Date of Completion: 11/18/2025

Operator Comment: Form 27 submitted 11/18/2025 doc# 404411658.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please see existing documentation submitted for further information. Working on providing manifests.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White Signed: \_\_\_\_\_

Title: HSE Date: 1/16/2026 5:17:04 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files