

Inspection Photos

01/14/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334283

Inspection Doc: 719200664

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334283



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334283



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334283



Photo 3: Photos showing an overview of the western interim area. This portion of the interim is progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334283



Photo 4: Photos showing an overview of the eastern fill slope. This portion of the interim appears to be dominated by undesirable weedy plant species; weed control is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources