

From: [Kosola - DNR, Jason](#)
To: [Matthew Baca](#)
Cc: steve.labowskie@state.co.us; [Jean Paradise-Slade](#)
Subject: Re: ECMC Inspections No Form 27
Date: Tuesday, January 13, 2026 11:59:46 AM
Attachments: [image001.png](#)
[image002.png](#)
[Official Logo of the Colorado Energy and Carbon Management Commission](#)
[Graphic 75 years, Serving Colorado since 1951, Celebrating our 75th anniversary in 2026](#)

Rule 913 mentions "decommissioning". I don't think that this activity would qualify as decommissioning and therefore no F27 is required.

Jason Kosola, P.G.
Environmental Protection Specialist - Southwest Colorado



P 719.641.0291
jason.kosola@state.co.us | <https://ecmc.colorado.gov/>



On Tue, Jan 13, 2026 at 10:57 AM Matthew Baca <matthew.baca@machnr.com> wrote:

Hello Steve-

I was wondering if you and Jason had a chance to visit on these inspections.

Matt

From: Matthew Baca
Sent: Tuesday, December 9, 2025 8:54 AM
To: steve.labowskie@state.co.us
Cc: 'jason.kosola@state.co.us' <jason.kosola@state.co.us>; Jean Paradise-Slade <jean.paradise-slade@machnr.com>
Subject: ECMC Inspections No Form 27

Steve-

As per our conversation yesterday, I have attached the two new inspections we received for No Form 27

filed. I visited with engineering and both of these locations were converted in our “Pump to Line Project”.


Interpretation was that even though the separator vessel was removed, the concrete slab was not, no Form 27 nor sampling was required. The “Pump to Line box” is sitting on the existing slab. This was an equipment substitution (like in kind replacement) rather than an equipment removal. In a full decommissioning, the slab would have been removed and sampling done; this will occur when the equipment and slab are removed permanently as part of the final reclamation associated with plug and abandonment.

Please let me know how to move forward on these two and any future inspections with this same conversion. There are approximately 30 locations completed and more to come 2026.

I’ve attached pics of the two locations showing the separator removed and the PTL box installed.

- **JT Morris A1 PTL conversion completed 2/12/2021.**
- **Piccoli Ranches 1 PTL conversion completed 8/11/2023**

Inspection Photos
name: PICCOLI RANCHES 1
LOCATION ID:325764




Inspection Photos
Well Name: JT MORRIS A 1
LOCATION ID:326015



Matthew Baca

Regulatory Compliance Analyst
405-882-6031
matthew.baca@machnr.com



NOTICE: This email has come from an **external source**. Do not click on links or open attachments unless you were expecting this email.