

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857



Photo # 2815 From entrance to location



Photo # 2816 From entrance to location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857




Photo # 2817 Location



Photo # 2818 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857



Photo # 2819 Location



Photo # 2820 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857




Photo # 2821 Location



Photo # 2822 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857



Photo # 2823 Location




Photo # 2824 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857



Photo # 2825 Location



Photo # 2826 Choke body on separator open ended/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC 697-13C 25 Pad

Location #: 335857



Photo # 2827 Choke body on separator open ended/wildlife hazard