

Inspection Photos

API: 071-06814

Operator: WAPITI OPERATING LLC

Inspection Date: 1/20/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the access road.



Inspection Photos



Photo 2. Facing southwest toward the wellsite.



Inspection Photos



Photo 3. Facing toward the fill slope of the location which is stabilized with vegetation.

