

Inspection Photos

API: 071-07312

Operator: WAPITI OPERATING LLC

Inspection Date: 1/20/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the wellsite.



Inspection Photos



Photo 2. Facing toward the pumpjack.



Inspection Photos



Photo 3. Facing toward the meter shed. Sign is posted at meter shed.



Inspection Photos



Photo 4. Facing toward the interim reclamation area which is stabilized with vegetation.

