

# Inspection Photos

01/14/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334782

Inspection Doc: 719200674

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 3:** Photos showing examples of wellhead signage that has slipped downwards, rendering it inconspicuous and difficult to read. Maintenance is required; comply with Rule 605.g.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 4:** Photos showing an overview of the northeastern and northern interim area, respectively. Rubber rabbitbrush is present and interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 5:** Photos showing examples of prickly Russian thistle, an undesirable plant species, is present in the interim areas. Weed control is required; comply with Rule 606.c.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334782



**Photo 6:** Photo showing some trash/debris that is present within the interim area. Comply with rule 606.d.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources