

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Stockpile onsite for years

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Weeds, torn fencing

Weeds

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Excavation with torn fencing

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Weeds

Inspection Photos
Location Name: Sack 1
Spill ID: 482167




Stockpile with liner



Torn stockpile liner

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Stockpile liner with ground exposed



Ripped stockpile liner

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Housekeeping issues

Stockpile liner

Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Stockpile with weeds and torn liner

Excavation with fallen fencing



Inspection Photos
Location Name: Sack 1
Spill ID: 482167



Fencing post trash



Excavation with fallen fencing, weeds