

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0509 Entrance to location



Photo # 0539 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0510 Location



Photo # 0523 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0532 Location



Photo # 0537 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0538 Location



Photo # 0563 NW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0564 NE corner of location



Photo # 0565 SE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0566 SW corner of location



Photo # 0508 Sign at entrance to location contains incorrect location ID #

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0518 Improperly covered wellhead cellar lacks wildlife egress/available for entry by wildlife




Photo # 0520 Unused chemical tank equipped with containment near wellhead on location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0534 Pump house door partially open to wildlife/available for entry by wildlife



Photo # 0536 Pump house hole open to wildlife/available for entry by wildlife

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0546 Open ended load line




Photo # 0548 Open holes in bottom of separator open to wildlife/available for entry by wildlife

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0552 Tunnel erosion on south side of location



Photo # 0555 Debris on location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0558 Debris on location



Photo # 0559 Debris on location Debris on location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC YELLOW CREEK #XOM 2-35-1 PAD

Location ID: 316678

Date: 01/5/2026



Photo # 0560 Debris on location



Photo # 0561 Debris on location